




LEGEND

- Federal Navigation Channel
- Cable Submarine
- Channel Centerline
- Contour Line
- Marine Infrastructure *
- Shoreline or Rip-rap
- Fixed Navigation Aids
- Obstruction Above Grade
- Obstruction Below Grade
- Red Navigation Buoy
- Green Navigation Buoy
- Shoaling Area
- Shoalest Sounding**

** Shoalest Sounding per Quarter per Reach
* Present at time of Survey

GRAPHIC SCALE

1" = 100' 100 0 100 200 Feet

N E S W

Notes:
Horizontal Datum: Rhode Island, RI-3800 NAD 83
Distance Units: U.S. Survey Feet
Vertical Datum: MLLW
Depth Units: U.S. Survey Feet
Vessel Name: Popham Beach
Sonar System: Reson T50 (Multibeam Sonar)
Sounding Frequency: 300 kHz
Survey Method: RTK, GPS TIDES
GPS_System: INS Integrated Reson (RTK)
RTK Base Station: MTS Smartnet Max
Software Used: Hypack
Sounding Sort Distance: 30'
Field Books: R&H 4985
Survey No.: RI_08_WWC_20250604_CS_035
Reference NOAA Chart No.: US5PVDFD

The information depicted on these charts represents the results of surveys made on the dates indicated, and can only be considered as indicating the conditions existing at that time.

General Notes
The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during June 2025. The positions of aids to navigation were located during survey operations, are provided for information only and should not be used for navigation. Orthoimagery is from a variety of sources and dates and is intended to portray general characteristics of the shoreline and other features. Temporal changes may have occurred since this dataset was collected and some parts may no longer be an accurate representation of the conditions. The information depicted on this map should NOT be used to determine volumes as volumes are determined from more sounding information than shown.

Project Remarks
Marine infrastructure and shoreline surveyed with ship-mounted Lidar. Submerged objects and features from previous survey displayed on plot. Objects above grade with red symbols, submerged wrecks above grade depths are labeled in blue.

Water Level Information
Tides were recorded using RTK GPS. NAVD88 to MLLW corrections were logged utilizing NOAA's V-Datum regional model Connecticut/Rhode Island Version 3.4. The corrections in the project area range from 2.32 feet to 2.33 feet. MLLW is below NAVD88; therefore, the correction should be added to NAVD88 to convert to MLLW (e.g.-10 NAV88 = -8 MLLW when using a 2-foot correction).

US Army Corps of Engineers
District: CENAE

DISCLAIMER
Access Constraints: The United States Government furnishes these data and information on an "as is" basis. The recipient agrees to understanding that the US Government makes no warranties, expressed or implied concerning the accuracy, completeness, reliability, or suitability of these data and information. It is agreed that the information and the data furnished. The United States shall be under no liability whatsoever to any individual or party for any loss from data made thereof. These data belong to the Government. Therefore the recipient fully agrees not to represent these data to anyone as other than government data. The recipient shall not transfer these data to others without also transferring this Disclaimer.

Distribution Liability: The data represents the results of data collected by the Army Corps of Engineers, New England District Engineers activity and indicates the general existing conditions. Engineers activity and indicates the general existing conditions. For navigation purposes, use only data identified as suitable for navigation accuracy specifications. The user is responsible for the results of any of the application of this data for other than its intended purpose.

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DISTRICT

SURVEYED BY: MJD
CHECKED BY: BTM
ISSUE DATE: 6/25/2025
SUBMITTED BY: Zachary McAvoy
APPROVED BY: NAE Survey
SIZE: ANSI D
MAP DOCUMENT: RI_08_WWC_20250604_CS_035

WARWICK COVE
WARWICK, RHODE ISLAND
CONDITION SURVEY


6-FOOT CHANNEL AND ANCHORAGES


File Name: **RI_08_WWC_20250604_CS_035**

SHEET IDENTIFICATION
Warwick Cove

Sheet 1 of 4

Revison Number: 5.24.09.03-5.24.09.03





LEGEND

- Federal Navigation Channel
- Cable Submarine
- Channel Centerline
- Contour Line
- Marine Infrastructure *
- Shoreline or Rip-rap
- Fixed Navigation Aids
- Obstruction Above Grade
- Obstruction Below Grade
- Red Navigation Buoy
- Green Navigation Buoy
- Shoaling Area
- Shoalest Sounding**

** Shoalest Sounding per Quarter per Reach
* Present at time of Survey

GRAPHIC SCALE

1" = 100' (100 0 100 200 Feet)

N E S W

Notes:
Horizontal Datum: Rhode Island, RI-3800 NAD 83
Distance Units: U.S. Survey Feet
Vertical Datum: MLLW
Depth Units: U.S. Survey Feet
Vessel Name: Popham Beach
Sonar System: Reson T50 (Multibeam Sonar)
Sounding Frequency: 300 kHz
Survey Method: RTK, GPS TIDES
GPS_System: INS Integrated Reson (RTK)
RTK Base Station: MTS Smartnet Max
Software Used: Hypack
Sounding Sort Distance: 30'
Field Books: R&H 4985
Survey No.: RI_08_WWC_20250604_CS_035
Reference NOAA Chart No.: US5PVDFD

The information depicted on these charts represents the results of surveys made on the dates indicated, and can only be considered as indicating the conditions existing at that time.

General Notes
The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during June 2025. The positions of aids to navigation were located during survey operations, are provided for information only and should not be used for navigation. Orthoimagery is from a variety of sources and dates and is intended to portray general characteristics of the shoreline and other features. Temporal changes may have occurred since this dataset was collected and some parts may no longer be an accurate representation of the conditions. The information depicted on this map should NOT be used to determine volumes as volumes are determined from more sounding information than shown.

Project Remarks
Marine infrastructure and shoreline surveyed with ship-mounted Lidar. Submerged objects and features from previous survey displayed on plot. Objects above grade with red symbols, submerged wrecks above grade depths are labeled in blue.

Water Level Information
Tides were recorded using RTK GPS. NAVD88 to MLLW corrections were logged utilizing NOAA's V-Datum regional model Connecticut/Rhode Island Version 3.4. The corrections in the project area range from 2.32 feet to 2.33 feet. MLLW is below NAVD88; therefore, the correction should be added to NAVD88 to convert to MLLW (e.g.-10 NAV88 = -8 MLLW when using a 2-foot correction).

US Army Corps of Engineers
District: CENAE

Distribution Liability: The data represents the results of data collection and analysis performed by the Corps of Engineers activity and indicates the general existing conditions. Any use of this data for purposes other than as stated may require additional verification, analysis, and/or specifications. The user is responsible for the results of any of the application of this data for other than its intended purpose.

DISCLAIMER
Access Constraints: The United States Government furnishes this data without warranty of any kind, either express or implied. By accepting this data, you agree to the following understanding that the US Government makes no warranties, expressed or implied concerning the accuracy, completeness, reliability, or suitability of this data for any purpose. Although the information and the data furnished. The United States shall be under no liability whatsoever to any individual or group entity for any claim made thereof. These data belong to the Government. Therefore the recipient fully agrees not to represent these data to anyone as other than government data. The recipient shall not transfer to others these data to others without also transferring this Disclaimer.

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DISTRICT

SURVEYED BY: MJD
CHECKED BY: BTM
ISSUE DATE: 6/25/2025
SUBMITTED BY: Zachary McAvoy
APPROVED BY: NAE Survey
SIZE: ANSI D
MAP DOCUMENT: RI_08_WWC_20250604_CS_035

WARWICK COVE
WARWICK, RHODE ISLAND
CONDITION SURVEY

6-FOOT CHANNEL AND ANCHORAGES

File Name: RI_08_WWC_20250604_CS_035

SHEET IDENTIFICATION
Warwick Cove

Sheet 2 of 4


Revison Number: 5.24.09.03-5.24.09.03

359,000 221,000 358,000

350,000 223,000 357,000

358,000 223,000 357,000 221,000

WARWICK
WARWICK NECK
WARWICK COVE
MARINA WINSTEADS
PILINGS (TYP.)
FLOOD
EBB
SUBMERGED CHAINS THROUGHOUT 6-FOOT EAST ANCHORAGE AND CHANNEL
SUBMERGED OBJECT BELOW GRADE (TYP.)
SUBMERGED BOAT ABOVE GRADE
6-FOOT EAST ANCHORAGE
DEBRIS AT OR NEAR GRADE
SUBMERGED BOAT BELOW GRADE
BREEZY POINT MARINA
RN-10
RN-12
GC-9
6-FOOT CHANNEL INNER REACH
6-FOOT CHANNEL CEDAR CREEK REACH
6-FOOT CHANNEL WARWICK COVE REACH
6-FOOT WEST ANCHORAGE
SUBMERGED OBJECT ABOVE GRADE (TYP.)
SUBMERGED BOAT ABOVE GRADE
BREWER GREENWICH BAY MARINA
SECOND POINT
CEDAR CREEK
PLEASURE MARINA
50+00
55+00
60+00
65+00
70+00
75+00
100'
300'



LEGEND

- Federal Navigation Channel
- Cable Submarine
- Channel Centerline
- Contour Line
- Marine Infrastructure *
- Shoreline or Rip-rap
- Fixed Navigation Aids
- Obstruction Above Grade
- Obstruction Below Grade
- Red Navigation Buoy
- Green Navigation Buoy
- Shoaling Area
- Shoalest Sounding**

** Shoalest Sounding per Quarter per Reach
* Present at time of Survey

GRAPHIC SCALE

1" = 100' 100 0 100 200 Feet

N E S W

Notes:
Horizontal Datum: Rhode Island, RI-3800 NAD 83
Distance Units: U.S. Survey Feet
Vertical Datum: MLLW
Depth Units: U.S. Survey Feet
Vessel Name: Popham Beach
Sonar System: Reson T50 (Multibeam Sonar)
Sounding Frequency: 300 kHz
Survey Method: RTK, GPS TIDES
GPS_System: INS Integrated Reson (RTK)
RTK Base Station: MTS Smartnet Max
Software Used: Hypack
Sounding Sort Distance: 30'
Field Books: R&H 4985
Survey No.: RI_08_WWC_20250604_CS_035
Reference NOAA Chart No.: US5PVDFD

The information depicted on these charts represents the results of surveys made on the dates indicated, and can only be considered as indicating the conditions existing at that time.

General Notes
The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during June 2025. The positions of aids to navigation were located during survey operations, are provided for information only and should not be used for navigation. Orthoimagery is from a variety of sources and dates and is intended to portray general characteristics of the shoreline and other features. Temporal changes may have occurred since this dataset was collected and some parts may no longer be an accurate representation of the conditions. The information depicted on this map should NOT be used to determine volumes as volumes are determined from more sounding information than shown.

Project Remarks
Marine infrastructure and shoreline surveyed with ship-mounted Lidar. Submerged objects and features from previous survey displayed on plot. Objects above grade with red symbols, submerged wrecks above grade depths are labeled in blue.

Water Level Information
Tides were recorded using RTK GPS. NAVD88 to MLLW corrections were logged utilizing NOAA's V-Datum regional model Connecticut/Rhode Island Version 3.4. The corrections in the project area range from 2.32 feet to 2.33 feet. MLLW is below NAVD88; therefore, the correction should be added to NAVD88 to convert to MLLW (e.g.-10 NAV88 = -8 MLLW when using a 2-foot correction).

US Army Corps of Engineers
District: CENAE

DISCLAIMER
Access Constraints: The United States Government furnishes this map and geospatial data and related products on the understanding that the US Government makes no warranties, expressed or implied concerning the accuracy, completeness, reliability, or suitability of this information. Any use of the information and the data furnished. The United States shall be under no liability whatsoever to any person by reason of any use made thereof. These data belong to the Government. Therefore the recipient fully agrees not to represent these data to anyone as other than Government data. The recipient shall not transfer these data to others without also transferring this Disclaimer.

Distribution Liability: The data represents the results of data collection and analysis performed by the U.S. Army Corps of Engineers activity and indicates the general existing conditions. Engineers activity and indicates the general existing conditions. The U.S. Army Corps of Engineers is not responsible for the results of any of the application of this data for other than its intended purpose.

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DISTRICT


SURVEYED BY: MJD
CHECKED BY: BTM
ISSUE DATE: 6/25/2025
SUBMITTED BY: Zachary McAvoy
APPROVED BY: NAE Survey
MAP DOCUMENT: RI_08_WWC_20250604_CS_035
SIZE: ANSI D


WARWICK COVE
WARWICK, RHODE ISLAND
CONDITION SURVEY
6-FOOT CHANNEL AND ANCHORAGES

File Name: RI_08_WWC_20250604_CS_035

SHEET IDENTIFICATION
Warwick Cove
Sheet 3 of 4

Revison Number: 5.24.09.03-5.24.09.03





LEGEND

- Federal Navigation Channel
- Cable Submarine
- Channel Centerline
- Contour Line
- Marine Infrastructure *
- Shoreline or Rip-rap
- Fixed Navigation Aids
- Obstruction Above Grade
- Obstruction Below Grade
- Red Navigation Buoy
- Green Navigation Buoy
- Shoaling Area
- Shoalest Sounding**

** Shoalest Sounding per Quarter per Reach
* Present at time of Survey

GRAPHIC SCALE

1" = 100' 100 0 100 200 Feet

N

Notes:
Horizontal Datum: Rhode Island, RI-3800 NAD 83
Distance Units: U.S. Survey Feet
Vertical Datum: MLLW
Depth Units: U.S. Survey Feet
Vessel Name: Popham Beach
Sonar System: Reson T50 (Multibeam Sonar)
Sounding Frequency: 300 kHz
Survey Method: RTK, GPS TIDES
GPS_System: INS Integrated Reson (RTK)
RTK Base Station: MTS Smartnet Max
Software Used: Hypack
Sounding Sort Distance: 30'
Field Books: R&H 4985
Survey No.: RI_08_WWC_20250604_CS_035
Reference NOAA Chart No.: US5PVDFD

The information depicted on these charts represents the results of surveys made on the dates indicated, and can only be considered as indicating the conditions existing at that time.

General Notes
The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during June 2025. The positions of aids to navigation were located during survey operations, are provided for information only and should not be used for navigation. Orthoimagery is from a variety of sources and dates and is intended to portray general characteristics of the shoreline and other features. Temporal changes may have occurred since this dataset was collected and some parts may no longer be an accurate representation of the conditions. The information depicted on this map should NOT be used to determine volumes as volumes are determined from more sounding information than shown.

Project Remarks
Marine infrastructure and shoreline surveyed with ship-mounted Lidar. Submerged objects and features from previous survey displayed on plot. Objects above grade with red symbols, submerged wrecks above grade depths are labeled in blue.

Water Level Information
Tides were recorded using RTK GPS. NAVD88 to MLLW corrections were logged utilizing NOAA's V-Datum regional model Connecticut/Rhode Island Version 3.4. The corrections in the project area range from 2.32 feet to 2.33 feet. MLLW is below NAVD88; therefore, the correction should be added to NAVD88 to convert to MLLW (e.g.-10 NAV88 = -8 MLLW when using a 2-foot correction).

US Army Corps of Engineers
District: CENAE

Distribution Liability: The data represents the results of data collection activities conducted by the U.S. Army Corps of Engineers activity and indicates the general existing conditions. Each user is responsible for determining the suitability of the data for their purposes. The user is responsible for the results of any of the application of this data for other than its intended purpose.

DISCLAIMER
Access Constraints: The United States Government furnishes this data without warranties of any kind whatsoever. It is understood that the US Government makes no warranties, expressed or implied concerning the accuracy, completeness, reliability, or suitability of this data, nor of its use across other information and the data furnished. The United States shall be under no liability whatsoever to any individual or group entity by reason of any use made thereof. These data belong to the Government. Therefore the recipient fully agrees not to represent these data to anyone as other than data received from the Government. The Government has no liability for these data to others without also transferring this Disclaimer.

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DISTRICT

SURVEYED BY: MJD
CHECKED BY: BTM
ISSUE DATE: 6/25/2025

SUBMITTED BY: Zachary McAvoy
APPROVED BY: NAE Survey

MAP DOCUMENT: RI_08_WWC_20250604_CS_035

SIZE: ANSI D

WARWICK COVE
WARWICK, RHODE ISLAND
CONDITION SURVEY

6-FOOT CHANNEL AND ANCHORAGES

File Name: RI_08_WWC_20250604_CS_035

SHEET IDENTIFICATION
Warwick Cove

Sheet 4 of 4

Revison Number: 5.24.09.03-5.24.09.03